

DATE 1010Z 16 AUG 61

**TOP SECRET**

1	4
2	5
3	6

**OPERATIONAL IMMEDIATE**

**OPERATIONAL IMMEDIATE**

IN 15242

25X1A TO : DIRECTOR  
 FROM :   
 ACTION: OPS (1,2,3,4,5)  
 INFO : S/C (6)  
 SP  
 25X1A TOR 1010Z 16 AUG 61

25X1A  
 25X1A  
 25X1A TO  
 25X1A  
 OPIM  INFO  CITE  016

ARTICLE 358 IN COMMISSION.

LOW LEVEL LIGHT BELIEVED TO HAVE BEEN CAUSED BY A PARTICLE OF TRASH AROUND FLOAT VALVE OR SMALL DEPOSIT OF ICE FROM WATER IN FUEL. SUMP TANK HAS BEEN DRAINED AND FUEL DRAINS AT LOW POINTS IN THE TANKS WILL BE DRAINED FOR A LONGER PERIOD ON PREFLIGHT TO GIVE ADDITIONAL ASSURANCE OF REMOVAL OF WATER IN THE FUEL.

END OF MESSAGE

**TOP SECRET**